


Mercedes-Benz

Mercedes-Benz (United Kingdom) Ltd

MERCEDES-BENZ CENTRE
Tongwell Milton Keynes MK15 8BA
Telephone: 0908 668899
Telex: 826904 Fax: 0908 664351



RRG/pap/2084B

Kleenoil Sales
Moor Lane Trading Estate
Sherburn-in-Elmet
Leeds
LS25 6ES

For the attention of Mr B M Cornett

Dear Sirs

Your letter dated 24 October '86 addressed to Daimler-Benz Department ZKD/G4 has been referred to us for attention.

On the basis of the limited information known to us, we can inform you that the terms of warranty for a vehicle fitted with your equipment remains in effect, except that we cannot be held responsible for any defects that are caused directly or indirectly by the above mentioned piece of equipment.

Yours faithfully
Mercedes-Benz (United Kingdom) Limited

A handwritten signature in black ink, appearing to read 'R R Griffiths'.

R R Griffiths
Service Warranty Manager

H. Leverton Limited
Goldard Road
Gildersome
Leeds LS27 7JG
Tel: 0532 634271
Fax: 0532 631482

The Slag Reduction Co.Ltd.,
Meadowbank House
Meadowbank Road
Rotherham
S61 2DY

For the attention of Mr. John Smith

Dear Sir,

Following your recent enquiry concerning the fitment of "Kleenoil" systems on your CAT machines, we are now pleased to confirm that such fitment will not invalidate any warranty claim. However, any damage resulting from the installation or operation of the "Kleenoil" system would be chargeable to yourselves.

We would ask that in the event of any engine failure during the warranty period, that Kleenoil Filtration Ltd., are contacted by yourselves at the outset to give them the option to investigate or not.

We hope that this meets with your requirements but if you have any further queries, please do not hesitate to contact the undersigned.

Yours faithfully
for H. Leverton Ltd.,


P.R. Butterworth
Product Support Department

VOLVO

Volvo Trucks (Great Britain) Limited
Irvine-Scotland

Your reference

Our reference

Mr. David Hall,
Kleenoil Filtration,
Moor Lane Industrial Estate,
Sherburn-in-Elmet,
Leeds.
LS25 6DL

Dear Mr. Hall,

With reference to your telephone enquiry regarding the use of your product, we would confirm that the fitting or use of this product does not, in itself, invalidate the warranty on the engine but we reserve the right to disclaim liability for failure which, in our opinion, can be attributed directly or indirectly to the failure of any non Volvo equipment fitted to the vehicle.

Yours faithfully,
VOLVO TRUCKS (GB) LIMITED



S. McGill (Secretary)
Service Department

KLEEN OIL FILTRATION LIMITED,
KLEEN OIL HOUSE, FAX 0977 685457
15 HIGH STREET, TEL 0977 682810
SOUTH MILFORD,
LEEDS LS25 5AA

Address
Kilwinning Road
Irvine
Ayrshire KA12 8TB

Telephone
0294-74120
Telex
77409
Telecopier
72840

Cables
Ailsatruk
Irvine

Directors
B. Brandtzaeg
S. Langenius
J.S. Arkell
B.W. Baker
Sven Käll
G. Renell
R.C. Smith

Regd. No.
43925
Scotland

Regd. Office
Irvine
Ayrshire



Harry H. McGinnis
Eagle Energy Products
Route 1 Box 387 B
Fairmont, WV 26554

Dear Mr. McGinnis,

Thank you for your letter to the Cummins Customer Assistance Center. I have reviewed the information sent to Pam Tripp regarding the Kleenoil microfiltration unit.

The warranty coverage provided by Cummins defines the responsibilities of Cummins and the customer in the event of a failure caused by a defect in Cummins' material or factory workmanship (a warrantable failure). Non-Cummins accessories are not warranted by Cummins and are the responsibility of the original equipment manufacturer.

Installing the Kleenoil filter will not void your Cummins warranty. However, if a failure occurs as a result of the microfiltration unit, Cummins is not responsible for warranty coverage. Warranty coverage, if applicable, would then need to be provided by the microfiltration unit manufacturer. A decision as to whether a particular failure is warrantable by Cummins will need to be made on a one on one basis. You can contact 1-800-DIESELS to determine warranty coverage for your Cummins Engine in regards to a particular situation.

If you have any questions please feel free to call me or any of the other CAC representatives at 1-800-DIESELS.

Sincerely,

A handwritten signature in cursive script that reads "Rodney A. Ewing".

Rodney A. Ewing
Cummins Engine Company
Mail Code 91200
309 Washington Street
Columbus, Indiana 47201
1-800-DIESELS



Mr B M Cornett
Managing Director
Kleenoil Filtration Ltd
Kleenoil House
15 High Street
South Milford LS25 5AA

Our Ref: JG/AB

Dear Mr Cornett

I have the following comments to make with respect to the installation of your Kleenoil by-pass filter on Deutz air cooled engines, after having studied both the construction and installation details laid down in your sales literature.

- 1) Your unit is an auxiliary by-pass system and as such does not affect or in any way replace our factory fitted filters.
- 2) I agree, that under extreme operating conditions, an additional by-pass oil filter system may well be of benefit to the engine.
- 3) Our standard maintenance schedules and filter change intervals (obtained from engine instruction manuals) should not be affected by the installation of your filter system.
- 4) If increased oil change intervals are prescribed by the operator, the resulting oil quality thereafter being his responsibility, he must regularly liaise with reputable laboratories and carry out thorough oil analysis tests.
- 5) The Deutz engine warranty is not materially affected as a result of fitting the Kleenoil by-pass filter system. However, Deutz Engines do not warrant failures proved to have been caused by, or resulting from the fitting of a Kleenoil filter.

Should you require any further information, please do not hesitate to contact me.

Yours sincerely

Rainer Kiess
Engineering Manager

APPENDIX 2