



Harry H. McGinnis
Eagle Energy Products
Route 1 Box 387 B
Fairmont, WV 26554

Dear Mr. McGinnis,

Thank you for your letter to the Cummins Customer Assistance Center. I have reviewed the information sent to Pam Tripp regarding the Kleenoil microfiltration unit.

The warranty coverage provided by Cummins defines the responsibilities of Cummins and the customer in the event of a failure caused by a defect in Cummins' material or factory workmanship (a warrantable failure). Non-Cummins accessories are not warranted by Cummins and are the responsibility of the original equipment manufacturer.

Installing the Kleenoil filter will not void your Cummins warranty. However, if a failure occurs as a result of the microfiltration unit, Cummins is not responsible for warranty coverage. Warranty coverage, if applicable, would then need to be provided by the microfiltration unit manufacturer. A decision as to whether a particular failure is warrantable by Cummins will need to be made on a one on one basis. You can contact 1-800-DIESELS to determine warranty coverage for your Cummins Engine in regards to a particular situation.

If you have any questions please feel free to call me or any of the other CAC representatives at 1-800-DIESELS.

Sincerely,

A handwritten signature in cursive script that reads "Rodney A. Ewing".

Rodney A. Ewing
Cummins Engine Company
Mail Code 91200
309 Washington Street
Columbus, Indiana 47201
1-800-DIESELS